

Fig 1 (PRIOR ART)




Fig 2




Fig 3




Fig 4

20200207 64474007




Fig 5A

2020-06-17 10:49:02




Fig 5B




Fig 6




Fig 7




Fig 8




Fig 9

20071749-020702

WORLD BANK

2020-06-17 2007




Figure 11: Basic Control with T34 vs Tad (F/A) schedule - PRIOR ART






Figure 13: Control with Bypass and Bleed Valves

20200207 64472007




Figure 14: Bypass Control Logic Details




Figure 15: Bleed Control Logic Details




Figure 16: Output power cycles resulting from the loss and re-establishing of the homogeneous combustion process wave.